

Safety Alert

Contractor TRI
Rental Truck Rollover

INCIDENT DETAILS


On 22 February 2026, a rented truck mixer carrying a 11 m³ of concrete rolled over While going to a customer site .The vehicle became unstable during the maneuver after entering the roundabout at a high speed 29km/h, exceeding the safe maneuvering speed.
As a result of the rollover, the Quality Control Technician who was travelling in the cabin with the driver sustained an elbow injury requiring hospital treatment and stitches

REVIEW POINTS FOR ALL SITES

- Are CEMEX fleet safety standards Applied to all rental trucks and drivers?
- Ensure telematics alerts are active, monitored, and acted upon.
- Review driving violations regularly and address non-compliance promptly.
- Have all drivers completed truck rollover prevention training and behavior monitoring?

KEY FINDINGS

✓	Driver and QC Technician were wearing seat belts at the time of the incident.
✓	The driver had successfully completed Defensive Driving and Truck Rollover Prevention training.
✗	Driver overconfidence influenced the decision to enter the roundabout at high speed.
✗	The Truck Mixer driver failed to comply with the roundabout speed limit, entering the roundabout at 29 km/h and this confirmed by GPS.



Watch Your Speed



Fit and Alert



Seatbelts Save Lives

14.07.2026