


# 8 Basic Steps of Isolation Procedure



## Safe Isolation at Cemex



### 1 Prepare

Assess the job to be done before starting.

### Notify

Inform all affected about equipment shutdown.



2



### 3 Isolate

Isolate equipment from all energy sources.

### Lock Out Tag Out

Apply individual padlocks on all relevant points.



4



### 5 Try Out

Verify power is isolated by operating equipment controls.

### Work Safely

Follow the correct procedures.



6



### 7 Clear

Ensure work area & equipment is clean, tidy and in a safe condition.

### Restore

Re-energize once all padlocks are removed and personnel notified.



8

