

### INCIDENT DETAILS

When the driver descended from the cab of the truck, he lost support with his right leg upon stepping onto the first step of the truck. As a result, he fell to ground level, with his body weight impacting the same leg, causing ligament injuries to the knee. The driver stated that he descended using the three points of contact and without haste. The condition of his boots was good, and the truck steps were equipped with anti-slip elements

### REVIEW POINTS FOR ALL SITES

- Remember that when getting in and out of a truck, special attention must be paid to placing the foot fully on each step, avoiding contact only with the toe.
- Before climbing up or down, check the cleanliness of the steps, boots, and grab handles. Remove any debris and ensure the steps are clear of materials.
- Check surroundings, keep hands free, use grab handles, wear proper PPE, and always maintain three points of contact when getting in and out of a truck.

### KEY FINDINGS

- |   |   |
|---|---|
| ✓ | The driver was wearing the necessary PPE, including safety boots.                           |
| ✓ | The driver was approved on the driver's validation system. Training and induction in place  |
| ✓ | The driver descended from the cabin using the 3 points of contact                           |
| ✗ | The driver did not place his foot correctly on the step, which caused the foot to not grip. |



Housekeeping



Safe Systems